

HUB 3-9 50BW KH07 A-SF

PARTS PRESENT IN BOX


1		IN BUCKET
2		LOADING JAW X2
3		CENTRE JAW X2
4		UNLOADING JAW X2
5		PRESSURE ROLLER SPACER X2
6		LOADING GUIDE X2
7		SHOE ASSEMBLY X2

COMMON PARTS NOT IN BOX

	USE	
8	56-18	STONE HOLDER X2

CONSUMABLES NOT IN BOX

9	54-86	BACKING PLATE X2
10	6*9*30	SUPERFINISH STONES
11		PRESSURE ROLLER X4



KEY ITEMS TO CHECK PER PART:

ALL	CONFIRM ALL PARTS HAVE THE CORRECT BEARING NUMBER ETCHED.
1	<p>BOTH LOCATING SPACERS ARE PRESENT</p> <p>NYLON SPACER IS NOT SIGNIFICANTLY WORN OR DAMAGED</p> <p>BUCKET IS SITTING FLUSH ON BASE PLATE</p> <p>PLATES ON EITHER SIDE NOT BENT OR DAMAGED</p> <p>NYLON/PLATES ARE NOT SPACED OUT</p>
2 - 4	<p>PLATES EITHER SIDE NOT BENT OR CRACKED</p> <p>BOTH BOLTS PRESENT FOR SECURING ONTO MACHINE</p> <p>NYLON JAWS NOT DAMAGED OR WARPED</p> <p>ALL BOLTS PRESENT AND UNDAMAGED</p>
5	<p>BOTH SPACERS ARE UNDAMAGED</p>
6	<p>LOADING GUIDES ARE UNDAMAGED/SIGNIFICANTLY WORN</p> <p>LOADING GUIDES ARE NOT BENT</p>
7	<p>SHOE TIPS UNDAMAGED</p> <p>WORK SUPPORTS PRESENT ON BOTH SETS OF SHOES</p> <p>COOLAND PIPE FITTING IS PRESENT AND UNDAMAGED</p> <p>LOCATING PADS ON SHOE BLOCKS UNDAMAGED</p> <p>ALL BOLTS UNDAMAGED AND SECURE</p> <p>COOLAND PLUG ON SHOES FITTED AND PRESENT</p>

